

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



1594 West North Temple, Suite 1210

PO Box 145801

Michael O. Leavitt

801-538-5340

Lowell P. Braxton Division Director

Governor

Salt Lake City, Utah 84114-5801

801-359-3940 (Fax) 801-538-7223 (TDD)

Partial: Complete: XXX Exploration: Inspection Date & Time: 7/16,22/99 / 1-3p.m., 8-1p.m.

Date of Last Inspection: 6/15/99

Mine Name: Willow Creek Mine County: Carbon Permit Number: ACT/007/038							
Permittee and/or Operator's Name: Cyprus Plateau Mining Corporation							
Business Address: 847 Northwest Highway 191, Helper, Utah 84526							
Type of Mining Activity: Underground XXX Surface Prep. Plant Other							
Company Official(s): Johnny Pappas							
State Officials(s): Peter Hess Federal Official(s): None							
Weather Conditions: Hot, 80's							
Existing Acreage: Permitted-14,670 Disturbed-206.7 Regraded- Seeded- Bonded-206.7							
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded							
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture							
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	,	EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[]	[]
2.	SIGNS AND MARKERS	XX	П	īī	Ti
3.	TOPSOIL	XX			\Box
4.	HYDROLOGIC BALANCE:			_	_
a.	DIVERSIONS	[XX]	\Box	\Box	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	ĹĬ	[_] [XX]	ΞĪ
c.	OTHER SEDIMENT CONTROL MEASURES	[XX] [XX] [XX] [XX] [XX] [XX]	\Box	L	\Box
d.	WATER MONITORING	[XX]	\Box		\Box
e.	EFFLUENT LIMITATIONS	[XX]	П	Ш	\Box
5.	EXPLOSIVES	[XX]	LÌ	Ĺĺ	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	\Box	\Box	ΞĬ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	ĪXXĪ	ĹÌ	[XX]	ĹĬ
8.	NONCOAL WASTE	[XX]	\Box		Π
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	[XX] [_]	\Box	[XX] [_] [_]	\Box
10.	SLIDES AND OTHER DAMAGE	Ц	[XX]	П	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	[XX]	\Box	ĹĬ
12.	BACKFILLING AND GRADING	\Box	[XX]	Ξ	
13.	REVEGETATION		[XX]	ĹĬ	ĹĬ
14.	SUBSIDENCE CONTROL	[XX]	П		Π
15.	CESSATION OF OPERATIONS		[XX]		\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	Ll	\Box
b.	DRAINAGE CONTROLS	[XX]		П	\Box
17.	OTHER TRANSPORTATION FACILITIES	[XX]	Ĺĺ	ĹĴ	ĹĬ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	ĹÌ	Ĺ	ĹĬ
19.	AVS CHECK (4th Quarter-April, May, June)(date)	[XX]	\Box	ĹĬ	ĹĬ
20.	AIR QUALITY PERMIT	ſΧΧÌ	\Box	Ĺ	ĹĬ
21.	BONDING & INSURANCE	īxxī	ΓĪ	īχχι	[]

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 7/16,22/99

(Comments are Numbered to Correspond with Topics Listed Above)

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Second quarter impoundment inspections for the site's numerous sediment containment ponds were conducted on June 18, 1999 by Mr. Johnny Pappas. No safety hazards or signs of instability were noted for any impoundments.

Mr. Pappas has informed me that pond 001A has not been properly constructed in that the primary spillway, which was installed, is too small. Also, the discharge elevation for the emergency spillway is incorrect. These items were discovered during the "as-built" field verification process; correction of these items is pending.

Pond 013A, which is the MSHA pond located at the toe of the School House Canyon refuse pile, is inspected on a monthly basis. No problems were noted during either the June or July inspection by Mr. Roland Tallerico. MSHA inspector Bruce Andrews inspected pond 013A on June 2, 1999.

No other problems were noted with any of the ponds during this inspection.

4d. HYDROLOGIC BALANCE: WATER MONITORING

The first quarter water monitoring report for the site was submitted to Ms. Pamela Grubaugh-Littig of the SLO-DOGM on May 10, 1999. Water samples for this report were taken during the months of February and March, 1999.

Discharge monitoring reports for the months of March, April, and May, 1999 were reviewed for the site's numerous UPDES out falls. None of the ponds discharged during these months; all reports were submitted in a timely fashion.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The second quarter refuse pile inspection for the School House Canyon waste rock disposal facility was conducted by Mr. Pappas on June 29, 1999. No apparent hazards or signs of instability were noted; all monitoring piezometers were noted as dry.

The second quarter inspection was P. E. certified by Mr. Richard B. White of EarthFax Engineering on July 6, 1999. No exceptions were indicated by Mr. White.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

The spill prevention control and countermeasure plan for the site was revised on March 5, 1999. Same was P.E. certified by Steve Jones, mining engineer on March 29, 1999.

21. BONDING AND INSURANCE

General liability insurance coverage has been renewed, effective June 30, 1999 through June 30, 2000. RAG American Coal Holding Inc. et al is listed as the assured firm on the renewal form. Policy # 6122944 is relative to the Willow Creek Mine and includes explosives coverage and liability amounts of \$6,000,000 for general aggregate.

#46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (RAG) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: August 16, 1999

Inspector's Signature:

Peter Hess